

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

BF291  
WNW  
1/4-1/2  
0.421 mi.  
2223 ft.

GETTY #00709  
2955 CROPSEY LANE  
BROOKLYN, NY

NY LTANKS  
NY Spills  
S103824176  
N/A

Site 8 of 8 in cluster BF

Relative:  
Higher

Actual:  
12 ft.

LTANKS:

Name: GETTY #709  
Address: 2955 CROPSEY AVENUE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0406923 / 2005-10-18  
Facility ID: 0406923  
Site ID: 178638  
Spill Date: 2004-09-23  
Spill Cause: Tank Overfill  
Spill Source: Gasoline Station or other PBS Facility  
Spill Class: C4  
Cleanup Ceased: Not reported  
SWIS: 2401  
Investigator: rjfeng  
Referred To: Not reported  
Reported to Dept: 2004-09-23  
CID: 404  
Water Affected: Not reported  
Spill Notifier: Responsible Party  
Last Inspection: Not reported  
Recommended Penalty: False  
Meets Standard: False  
UST Involvement: True  
Remediation Phase: 0  
Date Entered In Computer: 2004-09-23  
Spill Record Last Update: 2005-10-18  
Spiller Name: JAMES GERACI  
Spiller Company: GETTY #709  
Spiller Address: 2955 CROPSEY AV  
Spiller County: 001  
Spiller Contact: JAMES GERACI  
Spiller Phone: (718) 729-6500  
Spiller Extension: 270  
DEC Region: 2  
DER Facility ID: 110410  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
VOUGHT 08/31/2005 - Feng - Transferred from Vought to Feng.  
10/18/2005 - Feng - spill consolidated with spill #: 98-14319 in same  
location."

Remarks: "DRIVER SAYS HE CLEANED UP THE SPILL WITH SPILL PADS. NO OTHER  
RESOURCES AFFECTED. "

All Materials:

Site ID: 178638  
Operable Unit ID: 890275  
Operable Unit: 01  
Material ID: 484733  
Material Code: 0009  
Material Name: gasoline  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 10.00  
Units: G  
Recovered: 10.00

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Oxygenate: Not reported

Name: 2955 CROPSEY AVENUE  
Address: 2955 CROPSEY AVENUE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9213910 / 1993-04-15  
Facility ID: 9213910  
Site ID: 127938  
Spill Date: 1993-03-18  
Spill Cause: Tank Test Failure  
Spill Source: Gasoline Station or other PBS Facility  
Spill Class: C2  
Cleanup Ceased: 1993-04-15  
SWIS: 2401  
Investigator: O'DOWD  
Referred To: Not reported  
Reported to Dept: 1993-03-18  
CID: Not reported  
Water Affected: Not reported  
Spill Notifier: Tank Tester  
Last Inspection: Not reported  
Recommended Penalty: False  
Meets Standard: True  
UST Involvement: True  
Remediation Phase: 0  
Date Entered In Computer: 1993-03-30  
Spill Record Last Update: 1996-02-06  
Spiller Name: Not reported  
Spiller Company: GETTY  
Spiller Address: 30-23 GREENPOINT AVE.  
Spiller County: 001  
Spiller Contact: Not reported  
Spiller Phone: Not reported  
Spiller Extention: Not reported  
DEC Region: 2  
DER Facility ID: 110410  
DEC Memo: ""  
Remarks: "N.Y.C. F.D. NOTIFIED. UNCOVER TANK. ISOLATE & RECAP  
IT.4/12/93,2:20PM LM FOR ED WALDERON.4/15/93 RETESTED &  
PASSED.REPLACED FILL LINE, NO CONTAMINATION FOUND 4/1/93"

All TTF:

Facility ID: 9213910  
Spill Number: 9213910  
Spill Tank Test: 1541292  
Site ID: 127938  
Tank Number: Not reported  
Tank Size: 0  
Material: 0009  
EPA UST: Not reported  
UST: Not reported  
Cause: Not reported  
Source: Not reported  
Test Method: 00  
Test Method 2: Unknown  
Leak Rate: .00  
Gross Fail: Not reported  
Modified By: Spills  
Last Modified Date: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

All Materials:

Site ID: 127938  
Operable Unit ID: 977966  
Operable Unit: 01  
Material ID: 403658  
Material Code: 0009  
Material Name: gasoline  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: L  
Recovered: .00  
Oxygenate: Not reported

Name: 2955 CROPSEY AVENUE  
Address: 2955 CROPSEY AVENUE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9400403 / 1994-04-09  
Facility ID: 9400403  
Site ID: 127940  
Spill Date: 1994-04-09  
Spill Cause: Tank Overfill  
Spill Source: Gasoline Station or other PBS Facility  
Spill Class: C3  
Cleanup Ceased: 1994-04-09  
SWIS: 2401  
Investigator: O'DOWD  
Referred To: Not reported  
Reported to Dept: 1994-04-09  
CID: Not reported  
Water Affected: Not reported  
Spill Notifier: Responsible Party  
Last Inspection: Not reported  
Recommended Penalty: False  
Meets Standard: True  
UST Involvement: True  
Remediation Phase: 0  
Date Entered In Computer: 1994-04-11  
Spill Record Last Update: 2004-09-30  
Spiller Name: Not reported  
Spiller Company: SAME  
Spiller Address: Not reported  
Spiller County: 999  
Spiller Contact: Not reported  
Spiller Phone: Not reported  
Spiller Extention: Not reported  
DEC Region: 2  
DER Facility ID: 110410  
DEC Memo: ""  
Remarks: "DRIVER OVERFILLED TANK NYC FD @SCENE - CONTAINED W/SPEEDY DRY. NO CALL BACK."

All Materials:

Site ID: 127940  
Operable Unit ID: 994129  
Operable Unit: 01  
Material ID: 387719  
Material Code: 0009  
Material Name: gasoline

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Case No.: Not reported  
Material FA: Petroleum  
Quantity: -100.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

Name: GETTY  
Address: 2955 CROPSEY AVENUE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0305765 / 2005-10-18  
Facility ID: 0305765  
Site ID: 302596  
Spill Date: 2003-08-29  
Spill Cause: Tank Test Failure  
Spill Source: Gasoline Station or other PBS Facility  
Spill Class: B3  
Cleanup Ceased: Not reported  
SWIS: 2401  
Investigator: rjfeng  
Referred To: Not reported  
Reported to Dept: 2003-08-29  
CID: 252  
Water Affected: Not reported  
Spill Notifier: Tank Tester  
Last Inspection: Not reported  
Recommended Penalty: False  
Meets Standard: False  
UST Involvement: True  
Remediation Phase: 0  
Date Entered In Computer: 2003-08-29  
Spill Record Last Update: 2005-10-18  
Spiller Name: JOE DIMAGGIO  
Spiller Company: GETTY  
Spiller Address: 2955 CROPSEY AVE  
Spiller County: 001  
Spiller Contact: JOE DIMAGGIO  
Spiller Phone: (800) 249-7211  
Spiller Extention: Not reported  
DEC Region: 2  
DER Facility ID: 110410  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
VOUGHT 08/31/2005 - Feng - Transferred from Vought to Feng.  
10/18/2005 - Feng - spill consolidated with spill #: 98-14319 in same  
location."

Remarks: "TANK IS BEING REPAIRED AND WILL BE RE-TESTED TUES SEP 2ND-03."

All TTF:

Facility ID: 0305765  
Spill Number: 0305765  
Spill Tank Test: 1528628  
Site ID: 302596  
Tank Number: 1  
Tank Size: 3000  
Material: 0009  
EPA UST: Not reported  
UST: Not reported  
Cause: Not reported  
Source: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Test Method: 03  
Test Method 2: Horner EZ Check I or II  
Leak Rate: .00  
Gross Fail: Not reported  
Modified By: Spills  
Last Modified Date: Not reported

All Materials:

Site ID: 302596  
Operable Unit ID: 874222  
Operable Unit: 01  
Material ID: 503006  
Material Code: 0009  
Material Name: gasoline  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

Name: GETTY #709  
Address: 2955 CROPSEY AVENUE  
City, State, Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0410504 / 2005-10-18  
Facility ID: 0410504  
Site ID: 335471  
Spill Date: 2004-12-22  
Spill Cause: Tank Overfill  
Spill Source: Gasoline Station or other PBS Facility  
Spill Class: C4  
Cleanup Ceased: Not reported  
SWIS: 2401  
Investigator: rjfeng  
Referred To: Not reported  
Reported to Dept: 2004-12-22  
CID: 44  
Water Affected: Not reported  
Spill Notifier: Other  
Last Inspection: Not reported  
Recommended Penalty: False  
Meets Standard: False  
UST Involvement: True  
Remediation Phase: 0  
Date Entered In Computer: 2004-12-22  
Spill Record Last Update: 2005-10-18  
Spiller Name: MIKE CARRIER  
Spiller Company: GETTY #709

Spiller Address: 2955 CROPSEY AV  
Spiller County: 001  
Spiller Contact: MIKE CARRIER  
Spiller Phone: (518) 786-3200  
Spiller Extention: Not reported  
DEC Region: 2  
DER Facility ID: 110410  
DEC Memo: "08/31/2005 - Feng - Transferred from Vought to Feng. 10/18/2005 -  
Feng - spill consolidated with spill #: 98-14319 in same location."  
Remarks: "CUSTOMER OVERFILL, ALL CLEANED UP:"

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

All Materials:

Site ID: 335471  
Operable Unit ID: 1097533  
Operable Unit: 01  
Material ID: 577519  
Material Code: 0008  
Material Name: diesel  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 1.00  
Units: G  
Recovered: 1.00  
Oxygenate: Not reported

Name: GETTY #709  
Address: 2955 CROPSEY LANE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0511771 / 2006-01-12  
Facility ID: 0511771  
Site ID: 358000  
Spill Date: 2006-01-12  
Spill Cause: Tank Overfill  
Spill Source: Passenger Vehicle  
Spill Class: C4  
Cleanup Ceased: Not reported  
SWIS: 2401  
Investigator: rmpiper  
Referred To: Not reported  
Reported to Dept: 2006-01-12  
CID: 444  
Water Affected: Not reported  
Spill Notifier: Other  
Last Inspection: Not reported  
Recommended Penalty: Not reported  
Meets Standard: True  
UST Involvement: Not reported  
Remediation Phase: 0  
Date Entered In Computer: 2006-01-12  
Spill Record Last Update: 2006-01-12  
Spiller Name: Not reported  
Spiller Company: CUSTOMER OVERFUILL  
Spiller Address: Not reported  
Spiller County: 001  
Spiller Contact: MIKE CARR  
Spiller Phone: (518) 369-7822  
Spiller Extention: Not reported  
DEC Region: 2  
DER Facility ID: 308029  
DEC Memo: ""  
Remarks: "LESS THEN 1/2 GALLON AND IS CLEANED UP"

All Materials:

Site ID: 358000  
Operable Unit ID: 1115255  
Operable Unit: 01  
Material ID: 2105312  
Material Code: 0008  
Material Name: diesel  
Case No.: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material FA: Petroleum  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

Name: GETTY #709  
Address: 2955 CROPSEY LANE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0511821 / 2006-01-13  
Facility ID: 0511821  
Site ID: 358057  
Spill Date: 2006-01-13  
Spill Cause: Tank Failure  
Spill Source: Passenger Vehicle  
Spill Class: Not reported  
Cleanup Ceased: Not reported  
SWIS: 2401  
Investigator: JBVUGHT  
Referred To: Not reported  
Reported to Dept: 2006-01-13  
CID: 444  
Water Affected: Not reported  
Spill Notifier: Other  
Last Inspection: Not reported  
Recommended Penalty: False  
Meets Standard: False  
UST Involvement: False  
Remediation Phase: 0  
Date Entered In Computer: 2006-01-13  
Spill Record Last Update: 2006-01-13  
Spiller Name: MIKE CARR  
Spiller Company: GETTY #709  
Spiller Address: 2955 CROPSEY LANE  
Spiller County: 001  
Spiller Contact: MIKE CARR  
Spiller Phone: (518) 369-7822  
Spiller Extention: Not reported  
DEC Region: 2  
DER Facility ID: 308029  
DEC Memo: "1/13/06-Vought-Spill on concrete and no sewers or drains affected.  
Spill cleaned using speedy dry and closed by Vought."  
Remarks: "spilled out while filling buses all cleaned up"

All Materials:  
Site ID: 358057  
Operable Unit ID: 1115309  
Operable Unit: 01  
Material ID: 2105370  
Material Code: 0008  
Material Name: diesel  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 1.00  
Units: G  
Recovered: 1.00  
Oxygenate: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

SPILLS:

Name: GETTY #709  
Address: 2955 CROPSEY AVENUE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0511397 / 2006-01-03  
Facility ID: 0511397  
Facility Type: ER  
DER Facility ID: 110410  
Site ID: 357539  
DEC Region: 2  
Spill Cause: Other  
Spill Class: Not reported  
SWIS: 2401  
Spill Date: 2006-01-01  
Investigator: HRPATEL  
Referred To: Not reported  
Reported to Dept: 2006-01-01  
CID: 71  
Water Affected: Not reported  
Spill Source: Gasoline Station or other PBS Facility  
Spill Notifier: Local Agency  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2006-01-01  
Spill Record Last Update: 2006-01-03  
Spiller Name: MIKE CARR  
Spiller Company: GETTY #709  
Spiller Address: 2955 CROPSEY AV  
Spiller Company: 001  
Contact Name: MIKE CARR  
DEC Memo: "1/3/2006. Hiralkumar Patel. As per Mike Carr, there was a fault in dispenser and dispenser pan was filled with gas, and collected in secondary container. Dispenser is closed and all cleaned up. No Further Action Required. Case Closed."  
Remarks: "ACCUMULATION OF GAS IN DISPENSER PAN. CLEAN UP IN PROGRESS."

All Materials:

Site ID: 357539  
Operable Unit ID: 1114812  
Operable Unit: 01  
Material ID: 2104874  
Material Code: 0009  
Material Name: gasoline  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 2.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

Name: GETTY # 709  
Address: 2955 CROPSEY AVENUE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0511558 / 2006-01-06  
Facility ID: 0511558



Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Facility Type: ER  
DER Facility ID: 110410  
Site ID: 357745  
DEC Region: 2  
Spill Cause: Other  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2006-01-06  
Investigator: HRPATEL  
Referred To: Not reported  
Reported to Dept: 2006-01-06  
CID: 444  
Water Affected: Not reported  
Spill Source: Passenger Vehicle  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2006-01-06  
Spill Record Last Update: 2006-01-06  
Spiller Name: Not reported  
Spiller Company: CUSTOMER OVERFUELL  
Spiller Address: Not reported  
Spiller Company: 001  
Contact Name: MIKE CARR  
DEC Memo: "1/6/06-Hiralkumar Patel. As per Mike, a little splash during fueling in school bus. its all cleaned up with speedy dry. no further action required. case closed."

Remarks: "less then 1 quart: school bus and splashed back, cleaned up;"

All Materials:

Site ID: 357745  
Operable Unit ID: 1115021  
Operable Unit: 01  
Material ID: 2105074  
Material Code: 0008  
Material Name: diesel  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

Name: GETYY#709  
Address: 2955 CROPSEY AVENUE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0511723 / 2006-01-11  
Facility ID: 0511723  
Facility Type: ER  
DER Facility ID: 110410  
Site ID: 357935  
DEC Region: 2  
Spill Cause: Other  
Spill Class: C4  
SWIS: 2401

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Spill Date: 2006-01-11  
Investigator: SMSANGES  
Referred To: Not reported  
Reported to Dept: 2006-01-11  
CID: 444  
Water Affected: Not reported  
Spill Source: Gasoline Station or other PBS Facility  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2006-01-11  
Spill Record Last Update: 2007-02-22  
Spiller Name: Not reported  
Spiller Company: CUSTOMER OVERFILL  
Spiller Address: Not reported  
Spiller Company: 999  
Contact Name: MIKE CARR  
DEC Memo: ""  
Remarks: "all cleaned up no storm drains effected"

All Materials:

Site ID: 357935  
Operable Unit ID: 1115201  
Operable Unit: 01  
Material ID: 2105258  
Material Code: 0009  
Material Name: gasoline  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 2.00  
Units: G  
Recovered: 2.00  
Oxygenate: Not reported

Name: GETTY STATION  
Address: 2955 CROPSEY AVENUE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0307361 / 2004-08-02  
Facility ID: 0307361  
Facility Type: ER  
DER Facility ID: 110410  
Site ID: 127936  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: C5  
SWIS: 2401  
Spill Date: 2003-10-13  
Investigator: JBVOUGHT  
Referred To: Not reported  
Reported to Dept: 2003-10-13  
CID: 204  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2003-10-13  
Spill Record Last Update: 2004-08-02  
Spiller Name: MIKE CARR  
Spiller Company: GETTY STATION AT  
Spiller Address: 2955 CROPSEY AVENUE  
Spiller Company: 001  
Contact Name: MIKE CARR  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was VOUGHT 8/2/04-Vought-Letter from Tyree dated 7/26/04. These spills were reported because of product in spill buckets, poor housekeeping or human error. All product was properly cleaned and disposed of shortly after these spills were reported. Additionally, none of these releases caused products to contaminate the subsurface, groudwater or any sensitive receptors, such as drains or waterways. The Tyree Organization is requesting closure..... . Spill closed by Vought. Spill filed under #0307302. "  
Remarks: "ALL MATERIAL IS CONTAINED "

All Materials:

Site ID: 127936  
Operable Unit ID: 873846  
Operable Unit: 01  
Material ID: 500903  
Material Code: 0008  
Material Name: diesel  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 3.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

Site ID: 127936  
Operable Unit ID: 873846  
Operable Unit: 01  
Material ID: 500904  
Material Code: 0009  
Material Name: gasoline  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 3.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

Name: 2955 CROPSEY AVENUE  
Address: 2955 CROPSEY AVENUE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9400396 / 1994-04-09  
Facility ID: 9400396  
Facility Type: ER  
DER Facility ID: 110410  
Site ID: 127939  
DEC Region: 2

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Spill Cause: Unknown  
Spill Class: C3  
SWIS: 2401  
Spill Date: 1994-04-09  
Investigator: O'DOWD  
Referred To: Not reported  
Reported to Dept: 1994-04-09  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Fire Department  
Cleanup Ceased: 1994-04-09  
Cleanup Meets Std: True  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1994-04-11  
Spill Record Last Update: 2004-09-30  
Spiller Name: Not reported  
Spiller Company: UNK  
Spiller Address: Not reported  
Spiller Company: 999  
Contact Name: Not reported  
DEC Memo: ""  
Remarks: "NO DETAILS FD & DEP @ SCENE DEP RESPONDING TO DETERMINE - NO CALL BACK."

All Materials:

Site ID: 127939  
Operable Unit ID: 997887  
Operable Unit: 01  
Material ID: 387712  
Material Code: 0066A  
Material Name: unknown petroleum  
  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: -100.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

Name: GETTY#709  
Address: 2955 CROPSEY LANE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0701631 / 2007-05-16  
Facility ID: 0701631  
Facility Type: ER  
DER Facility ID: 308029  
Site ID: 381182  
DEC Region: 2  
Spill Cause: Housekeeping  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2007-05-09  
Investigator: smsanges  
Referred To: Not reported  
Reported to Dept: 2007-05-09  
CID: 444

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Water Affected: Not reported  
Spill Source: Gasoline Station or other PBS Facility  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: Not reported  
UST Trust: Not reported  
Remediation Phase: 0  
Date Entered In Computer: 2007-05-09  
Spill Record Last Update: 2007-05-16  
Spiller Name: MIKE CARR  
Spiller Company: GETTY#709  
Spiller Address: 2955 CROPSEY LANE  
Spiller Company: 001  
Contact Name: MIKE CARR  
DEC Memo: "minor spill - all cleaned"  
Remarks: "LESS THEN 1 GALLON: PENDING REPAIRS"

All Materials:

Site ID: 381182  
Operable Unit ID: 1138648  
Operable Unit: 01  
Material ID: 2128644  
Material Code: 0009  
Material Name: gasoline  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

Name: LUKE OIL  
Address: 2955 CROPSEY LANE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0711055 / 2008-01-18  
Facility ID: 0711055  
Facility Type: ER  
DER Facility ID: 308029  
Site ID: 392469  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: Not reported  
SWIS: 2401  
Spill Date: 2008-01-18  
Investigator: jbvought  
Referred To: Not reported  
Reported to Dept: 2008-01-18  
CID: 444  
Water Affected: Not reported  
Spill Source: Gasoline Station or other PBS Facility  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: Not reported  
Remediation Phase: 0

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Date Entered In Computer: 2008-01-18  
Spill Record Last Update: 2008-01-18  
Spiller Name: HECTOR  
Spiller Company: LUKE OIL  
Spiller Address: 2955 CROPSEY LANE  
Spiller Company: 001  
Contact Name: HECTOR  
DEC Memo: "01/18/08-Vought-Duty desk officer. Called and spoke to Hector Campineir and spill was on concrete, was cleaned using absorbent material and no sewers or drains affected. Spill closed by Vought."  
Remarks: "A PLUG IN FILL AREA WAS OPEN AND SHOULD HAVE BEEN CLOSED AND CAUSED SPILL AND IS ALL CLEANED UP"

All Materials:

Site ID: 392469  
Operable Unit ID: 1149474  
Operable Unit: 01  
Material ID: 2140000  
Material Code: 0008  
Material Name: diesel  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 2.00  
Units: G  
Recovered: 2.00  
Oxygenate: Not reported

Name: GETTY #709  
Address: 2955 CROPSEY LANE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0605909 / 2008-10-24  
Facility ID: 0605909  
Facility Type: ER  
DER Facility ID: 308029  
Site ID: 369173  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2006-08-22  
Investigator: smsanges  
Referred To: Not reported  
Reported to Dept: 2006-08-22  
CID: 444  
Water Affected: Not reported  
Spill Source: Gasoline Station or other PBS Facility  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: True  
Remediation Phase: 0  
Date Entered In Computer: 2006-08-22  
Spill Record Last Update: 2008-10-24  
Spiller Name: MIKE CARR  
Spiller Company: GETTY #709  
Spiller Address: 2955 CROPSEY LANE  
Spiller Company: 001

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Contact Name: MIKE CARR  
DEC Memo: "Tyree report says: Sump in contained. Metro did a Tank Test (passed)  
All lines and leak detectors were also tested and passed."  
Remarks: "LESS THEN 1 GALLON AND SHEEN OF DIESEL: ALL CONTAINED"

All Materials:

Site ID: 369173  
Operable Unit ID: 1127016  
Operable Unit: 01  
Material ID: 2116588  
Material Code: 0008  
Material Name: diesel  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

Name: GETTY #00709  
Address: 2955 CROPSEY LANE  
City, State, Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0605930 / 2006-08-23  
Facility ID: 0605930  
Facility Type: ER  
DER Facility ID: 308029  
Site ID: 369195  
DEC Region: 2  
Spill Cause: Other  
Spill Class: Not reported  
SWIS: 2401  
Spill Date: 2006-08-23  
Investigator: JBVOUGHT  
Referred To: Not reported  
Reported to Dept: 2006-08-23  
CID: 444  
Water Affected: Not reported  
Spill Source: Gasoline Station or other PBS Facility  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2006-08-23  
Spill Record Last Update: 2006-08-23  
Spiller Name: ED WALDRON  
Spiller Company: GETTY #00709  
Spiller Address: 2955 CROPSEY LANE  
Spiller Company: 001  
Contact Name: ED WALDRON  
DEC Memo: "08/23/06-Vought-Off hours repsonder. Vought called Waldron and as  
per Waldron FDNY was onsite and left by time of call. FDNY washed  
spill down sewer. Vought called DEP and reported discharge. No spill  
to soil or groundwater. Spill closed by Vought."

Remarks: "DRIVER FORGOT TO TIGHTEN HIS STICK BOX: ALL CLEANED UP: NO WATERWAYS  
EFFECTED"

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

All Materials:

Site ID: 369195  
Operable Unit ID: 1127038  
Operable Unit: 01  
Material ID: 2116612  
Material Code: 0009  
Material Name: gasoline  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 5.00  
Units: G  
Recovered: 5.00  
Oxygenate: Not reported

Name: GETTY #709  
Address: 2955 CROPSEY LANE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0605878 / 2006-12-08  
Facility ID: 0605878  
Facility Type: ER  
DER Facility ID: 308029  
Site ID: 369136  
DEC Region: 2  
Spill Cause: Other  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2006-08-22  
Investigator: SMSANGES  
Referred To: Not reported  
Reported to Dept: 2006-08-22  
CID: 444  
Water Affected: Not reported  
Spill Source: Gasoline Station or other PBS Facility  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2006-08-22  
Spill Record Last Update: 2006-12-08  
Spiller Name: WAQUAS  
Spiller Company: GETTY #709  
Spiller Address: 2955 CROPSEY LANE  
Spiller Company: 001  
Contact Name: WAQUAS  
DEC Memo: "Spill was called in by Metro during a line test. Diesel was in the submersible sump. Plug in system was open. Plug replaced, line was retested & passed Area was vac'ed out"

Remarks: "GAS CAME OUT OF PLUG WHILE WORKING ON PUMP: ALL CLEANED UP"

All Materials:

Site ID: 369136  
Operable Unit ID: 1126984  
Operable Unit: 01  
Material ID: 2116552  
Material Code: 0009  
Material Name: gasoline



Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Case No.: Not reported  
Material FA: Petroleum  
Quantity: 3.00  
Units: G  
Recovered: 3.00  
Oxygenate: Not reported

Name: GETTY #709  
Address: 2955 CROPSEY LANE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0804815 / 2008-08-01  
Facility ID: 0804815  
Facility Type: ER  
DER Facility ID: 308029  
Site ID: 401799  
DEC Region: 2  
Spill Cause: Human Error  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2008-07-28  
Investigator: smsanges  
Referred To: Not reported  
Reported to Dept: 2008-07-28  
CID: 71  
Water Affected: Not reported  
  
Spill Source: Gasoline Station or other PBS Facility  
Spill Notifier: Local Agency  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: Not reported  
Remediation Phase: 0  
Date Entered In Computer: 2008-07-28  
Spill Record Last Update: 2008-08-01  
Spiller Name: MIKE CARR'  
Spiller Company: GETTY #709  
Spiller Address: 2955 CROPSEY LANE  
Spiller Company: 001  
Contact Name: MIKE CARR'  
DEC Memo: "minor spill - all cleaned"  
Remarks: "POOR HOUSEKEEPING. CLEANED UP"

All Materials:  
Site ID: 401799  
Operable Unit ID: 1158574  
Operable Unit: 01  
Material ID: 2149651  
Material Code: 0008  
Material Name: diesel  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 1.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

[Click this hyperlink](#) while viewing on your computer to access  
9 additional NY SPILL: record(s) in the EDR Site Report.